Average Surface Closing Pressure

(GL-16 3/4-5000 Standard Hook-up)



CAUTION : Due to limiting properties of casing, closure should be done carefully, using initial closing pressure to prevent collapse of casing.
The closing pressures shown are initial closing pressures for most casing at O (zero) well pressure. Slightly higher closing pressure may be required for seal-off at higher well pressures.

NOTE : Pressures shown are average. Actual pressure required to affect seal-off will vary slightly with each individual packing unit.